



13. Closeup of girder fascia and plinth deterioration undermining bridge posts.



14. Close up of girder fascia and plinth deterioration undermining bridge posts.

Bridge File No.: 1331-2
Date: March 4, 23025
Pictures By: G. Roberts



Highway: Local Road
Location: Cayley
Stream: Mosquito Creek



15. Close up of girder fascia deterioration with visible rebar stirrups and undermining posts.